

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

298
SW
1/4-1/2
0.447 mi.
2358 ft.

PRIVATE RESD
2925 W 19TH ST
BROOKLYN, NY

NY Spills S117394163
N/A

Relative:
Higher

Actual:
5 ft.

SPILLS:

Name: PRIVATE RESD
Address: 2925 W 19TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1409724 / 2017-06-19
Facility ID: 1409724
Facility Type: ER
DER Facility ID: 458294
Site ID: 503366
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2014-12-31
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2014-12-31
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2014-12-31
Spill Record Last Update: 2017-06-19
Spiller Name: RALPH PANTONI
Spiller Company: PRIVATE RESD
Spiller Address: 2925 W 19TH ST
Spiller Company: 999
Contact Name: RALPH PANTONI
DEC Memo: "12/31/14 TJD Teleconference with Ralph @Action Environmental - he states that the spill location is Coney Island Hospital which is currently undergoing construction work. The general contractor at the hospital is Access Construction, a subcontractor (Agustowitz Excavation) struck a previously unknown 550 UST while excavating. The tank was filled with oily water and was punctured causing a discharge of approximately 10 gallons to surrounding soils. During removal of the tank a second 550 UST was discovered. Both tanks have been removed from the excavation as they were not connected to any fuel burning equipment. Ralph reports that Action was retained as a subcontractor to Agustowitz Excavation and removed an estimated 6 cu yds of petroleum impacted soils to a clean endpoint. Action still has personnel onsite - DeMeo has requested endpoint samples (base/sidewalls) be collected and analyzed for EPA methods 8260/8270, a site map, brief narrative summary and disposal documentation be provided in support of spill closure. Ralph inquired if the PBS registration needs to be updated - DeMeo has informed him that these tanks will need to be added and removed from the facilities PBS registration in accordance with applicable regulations. Ralph did not have the contact information for the above referenced contractors at

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

the time of phone conversation and states he will e-mail DeMeo with this information. No letter sent as the project is substantially complete. 6/19/17 TJD File review. Contractor has not submitted a closure report for this site. A review of available documentation reveals a sample map with corresponding laboratory data has been received. Concentrations of target analytes are within acceptable concentrations. As the documentation indicates, the reported spill is associated with the discovery and removal of previously unknown 550 gallon UST's during a capital project at the Coney Island Hospital. One 550 UST was punctured during removal by the contractor causing an estimated 10 gallons of oily water to discharge onto surrounding soils. Due to the nature of the reported event and the remedial activities taken by the involved contractor this spill is administratively closed. All documentation has been uploaded to DECDOCS."

Remarks:

"UST removal with impacted soil. Cleanup is pending."

All Materials:

Site ID: 503366
Operable Unit ID: 1252722
Operable Unit: 01
Material ID: 2254852
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: Not reported
Oxygenate: Not reported